

QUANTITY CONTROL PROGRAM

Weights and Measures Inspectors inspect the packaged goods to verify the weight, volume or count of the packaging. All packaged commodities must have a label indicating the net quantity on the principal display side of the package, which is the side of the package that consumers see. The net quantity excludes any wrapping or container for the product. Weights and Measures quantity control inspectors test these products using statistical methods to verify that the packages hold the correct amount and the attached label meets all requirements Federal [Uniform Packaging and Labeling Regulation](#), and California's [Fair Packaging and Labeling Act](#).

Weights and Measures inspectors conduct undercover test sales and purchases to verify that weighing and measuring devices are being used properly, and the correct tare weight (the weight for any sanitary paper, wrapping, cup, or container) is used.



Helpful Links

[DMS Consumer Information Guide](#)

[DMS Business Information Guide](#)

[NIST Handbook 133](#)

Get What You Pay For

All customers are entitled to get the amount of product they pay for. If you

have any concerns about any transactions please submit the [online complaint form](#).